

How to read MPC56xxx CPU by Carprotool Programmer

1. Connect all test points like on connection diagrams
2. Connect external small black power adapter to CPT
3. Connect RJ48 Cable to CPT Programmer
4. Select correct CPU name and CPU bank (CRASH DATA available in bank1 64kb)
5. Click on Read button (wait about 20 sec. for read data)
6. Click save button and save file on your hdd

How to write data with verification to CPU MPC56xxx by CarProTool Programmer

1. Disconnect and connect again RJ48 Cable in CPT
2. Click Open button and add correct file to buffer
3. Select Auto Verify (available in Write button from right site)
4. Click Write button (wait for write data and verification)

Watch video: <https://youtu.be/zHfFndONsPM>



Best Regards
CarProTool Support Team

