

AlfaRomeo GM Multec 29F010
AlfaRomeo GM Multec MC68HC11F1
AlfaRomeo Hitachi 24C02
AlfaRomeo Hitachi 93C46
AlfaRomeo Bosch EDC15C5 24C04
AlfaRomeo Bosch EDC15C6 95080
AlfaRomeo Bosch EDC15C7 95080
AlfaRomeo Bosch EDC16C39 95320
AlfaRomeo Bosch EDC16C39 95640
AlfaRomeo Bosch EDC16C8 95160
AlfaRomeo Bosch EDC16C9 95160
AlfaRomeo Magneti Marelli IAW 18F.XX 27C512
AlfaRomeo Magneti Marelli IAW 18F.XX MC68HC11F1
AlfaRomeo Magneti Marelli IAW 4Q-J-W MC68HC11E1
AlfaRomeo Magneti Marelli IAW 8F.XX MC68HC11F1
AlfaRomeo Bosch M2.10.3 24C02
AlfaRomeo Bosch M2.10.4 24C02
AlfaRomeo Bosch M2.7 27C256
AlfaRomeo Bosch ME 7.1.1 95080
AlfaRomeo Bosch ME 7.9.10 95160
AlfaRomeo Bosch MED 7.1.1 95080
AlfaRomeo Bosch MED 7.6.1 95080
AlfaRomeo Bosch MED 7.6.2 95080
AlfaRomeo Hitachi MFI 003BC2 93C46(59C11)
AlfaRomeo Bosch MSA11 EDC1.3.1 93C46
Aprilia Magneti Marelli 59M Hybrid ST10F269
Aprilia Magneti Marelli 59M Hybrid v2 ST10F269
Aprilia Magneti Marelli 5AM Hybrid ST10F269
Aprilia Magneti Marelli 5AM Hybrid v2 ST10F269
Aprilia Magneti Marelli 5DM Hybrid ST10F269
Aprilia Magneti Marelli 5DM Hybrid v2 ST10F269
Audi Digifant 3.2 27C256
Audi Siemens 5WP4 SIMOS 1.X 93C56
Audi Siemens 5WP4 SIMOS 3.X 93C76
Audi Bosch EDC16CP34 95320
Audi Bosch EDC16U1 95320
Audi Bosch EDC16U31 95320
Audi Bosch EDC16U34 95320
Audi Bosch M2.3.1 24C02
Audi Bosch M2.3.2 27C512
Audi Bosch M3.8.X v1 24C02
Audi Bosch M3.8.X v2 24C02
Audi Bosch M5.4.1 24C02
Audi Bosch M5.9.2 24C02
Audi Bosch M7.X.X 95040
Audi Bosch M7.X.X 95080
Audi Bosch M7.X.X 95160
Audi Bosch MED 9.5.10 95080
Audi Bosch MSA 15.X 24C02
Audi Bosch MSA11 EDC1.3.1 93C46
Audi Siemens SIMOS 7.X 93C86
Audi Siemens SIMOS 8.1 93C86
Audi Siemens SIMOS 9.1 93C86
BMW Siemens BMS 46 29F200

BMW Bosch EDC15C4 95P08
BMW Bosch EDC15M-6 DDE 3.0 24C04
BMW Bosch M 1.7.2 27C256
BMW Siemens MMS 50 29F200
BMW Siemens MMS 52 29F200
BMW Siemens MS 41.0 DME 29F200
BMW Siemens MS 42 29F400
BMW Bosch MSA 11 EDC1.3.1 93C46
BMW Bosch MSA 15.5 93C46
Blazer Bosch M2.8 24C02
Chevrolet GM Multec 29F010
Chevrolet GM Multec MC68HC11F1
Chevrolet Bosch M2.8 24C02
Chevrolet Aveo Delphi Korea Hybrid 1400cc 95020
Chevrolet Matiz Kemsco 29F400
Chrysler Bosch EDC MSA 15.5-5.3 v1 24C04
Chrysler Bosch EDC MSA 15.5-5.3 v2 24C04
Chrysler Bosch EDC MSA 15.5-5.5 v1 24C04
Chrysler Bosch EDC MSA 15.5-5.5 v2 24C04
Chrysler Bosch EDC15C2 95P08
Chrysler Siemens SIRIUS 34 29F400
Chrysler Chrysler White Box MC68HC11E9
Citroen Magneti Marelli 1AF.13-14-15-16-17 27C512
Citroen Magneti Marelli 48P.10 29F200
Citroen Magneti Marelli 48P.3X 95080
Citroen Magneti Marelli 48P2.XX 29F400
Citroen Magneti Marelli 4MP.XX 29F200
Citroen Magneti Marelli 4MP2.XX 29F200
Citroen Magneti Marelli 5NP 95160
Citroen Bosch EDC15C2 1socket 29F400
Citroen Bosch EDC15C2 3socket 29F400
Citroen Bosch EDC15C2 3socket 95080
Citroen Bosch EDC15C6 EURO3 95P08
Citroen Bosch EDC15C7 95P08
Citroen Bosch EDC15C7 EURO3 29F400
Citroen Bosch EDC16C3 95160
Citroen Bosch EDC16C34 95160
Citroen Bosch EDC16C34 virgin 95160
Citroen Lucas EPIC MC68HC11E9
Citroen Magneti Marelli G6 MC68HC11A1
Citroen Magneti Marelli IAW 1AP.20 TMS
Citroen Magneti Marelli IAW 1AP.40 TMS
Citroen Magneti Marelli IAW 1AP.41 TMS
Citroen Magneti Marelli IAW 1AP.43 TMS
Citroen Magneti Marelli IAW 1AP.80 TMS
Citroen Magneti Marelli IAW 1AP.81 TMS
Citroen Magneti Marelli IAW 1AP.83 TMS
Citroen Magneti Marelli IAW 1AP.90 TMS
Citroen Magneti Marelli IAW 8P.XX MC68HC11A1
Citroen Bosch M7.4.4 95080
Citroen Bosch M7.4.4 v2 95080
Citroen Bosch MA 3.0 93C46
Citroen Bosch MA 3.1 93C46
Citroen Bosch MA 3.2 93C46

Citroen Bosch ME 7.4.4 29F400
Citroen Bosch ME 7.4.4 95160
Citroen Bosch ME 7.4.4 v2 95160
Citroen Bosch Motronic MP 3.1 93C46
Citroen Bosch Motronic MP 3.2 93C46
Citroen Bosch Motronic MP 5.1 93C46
Citroen Bosch Motronic MP 5.1.1 93C46
Citroen Bosch Motronic MP 5.2 93C46
Citroen Bosch Motronic MP 7.0 24C02
Citroen Bosch Motronic MP 7.2 24C02
Citroen Bosch Motronic MP 7.3 24C02
Citroen Bosch MSA 11 EDC1.3.8 93C46
Citroen Sagem S2000 95080
Citroen Siemens SID 801 29F400
Citroen Siemens SID 801 93C56
Citroen Siemens SID 801A 29F400
Citroen Siemens SID 801A 93C56
Citroen Siemens SID 802 29F400
Citroen Siemens SID 804 29F400
Citroen Siemens SID 806 29F400
Citroen Sagem SL96 1x28F512 TMS374
Citroen Sagem SL96 2x28F512 TMS374
Citroen C1 Valeo IMMO 1000cc Virgin 24C04
Citroen C2 Siemens BSI Virgin 95128
Citroen C3 Siemens BSI Virgin 95160
Citroen C4 BSI Virgin 95128
Citroen XARA Valeo BSI 2002 Virgin 95040
Citroen XARA Valeo BSI 2003 Virgin 95040
Dacia Delphi TRW 95080
Dacia Delphi DCM 1.2 95160
Dacia Delphi DCM 1.2 v2 95160
Dacia Delphi TRW DDCR 95080
Dacia Siemens EMS 3132 29F200
Dacia Siemens SIRIUS 32 29F200
Dacia Siemens SIRIUS 32 without CAN 29F200
Dacia Siemens SIRIUS 34 29F200
Dacia Siemens SIRIUS 34 29F400
Daewoo Siemens TMS374
Daewoo Kemsco D3 29F200
Daewoo Delphi-Delco Hybrid 95020
Daewoo GM Multec socket blue and grey 27C256
Daewoo GM Multec socket blue and grey MC68HC11F1
Daewoo GM Multec socket light blue MC68HC11F1
Daewoo GM Multec socket red and brown MC68HC11F1
Daewoo GM Multec socket red and white MC68HC11F1
Daf Bosch EDC7 95640
Daf Bosch EDC7 v2 95640
Daf Bosch MS 6.2 24C16
Dodge Bosch EDC MSA 15.5-5.3 24C04
Dodge Bosch EDC MSA 15.5-5.3 v2 24C04
Dodge Bosch EDC MSA 15.5-5.5 24C04
Dodge Bosch EDC MSA 15.5-5.5 v2 24C04
Ducati Magneti Marelli 59M Hybrid ST10F269
Ducati Magneti Marelli 59M Hybrid v2 ST10F269

Ducati Magneti Marelli 5AM Hybrid ST10F269
Ducati Magneti Marelli 5AM Hybrid v2 ST10F269
Fendt Bosch MS 6.4 24C16
Fiat Hitachi 24C02
Fiat Hitachi 59C11
Fiat Hitachi 93C46
Fiat Magneti Marelli 1AB.XX 27C512
Fiat Magneti Marelli 1AF.13-14-15-16-17 27C512
Fiat Magneti Marelli 1AG7.XX MC68HC11F1
Fiat Magneti Marelli 48P 29F400
Fiat Magneti Marelli 48P.3X 95080
Fiat Magneti Marelli 49F 95040
Fiat Magneti Marelli 49F v1 95040
Fiat Magneti Marelli 49F v2 95040
Fiat Magneti Marelli 4AF 95160
Fiat Magneti Marelli 4AF v2 95160
Fiat Magneti Marelli 4EF 95080
Fiat Magneti Marelli 4EF v2 95080
Fiat Magneti Marelli 4GF 95040
Fiat Magneti Marelli 4GF v2 95040
Fiat Magneti Marelli 4MP 29F400
Fiat Magneti Marelli 59F Hybrid HW v.100 ST10F269
Fiat Magneti Marelli 59F Hybrid HW v.100 v2 ST10F269
Fiat Magneti Marelli 59FBTX 95160
Fiat Magneti Marelli 5AF Hybrid ST10F269
Fiat Magneti Marelli 5AF Hybrid v2 ST10F269
Fiat Magneti Marelli 5NF 95160
Fiat Magneti Marelli 5NF v2 95160
Fiat Magneti Marelli 5SF 95160
Fiat Magneti Marelli 5SF3 ST10F280
Fiat Magneti Marelli 5SF8 ST10F296
Fiat Magneti Marelli 5SF9 ST10F296
Fiat Visteon DCU 102 ST10F276
Fiat Lucas DCU3F 95080
Fiat Lucas DCU3F v2 95080
Fiat Bosch EDC15C2 95P08
Fiat Bosch EDC15C39 95320
Fiat Bosch EDC15C39 95640
Fiat Bosch EDC15C5 (5 socket) 24C04
Fiat Bosch EDC15C6 95P08
Fiat Bosch EDC15C7 95P08
Fiat Bosch EDC15C8 95160
Fiat Bosch EDC15C8 95320
Fiat Bosch EDC16C9 95160
Fiat Lucas EPIC MC68HC11E9
Fiat Magneti Marelli IAW 16F.XX MC68HC11F1
Fiat Magneti Marelli IAW 18F.XX MC68HC11F1
Fiat Magneti Marelli IAW 1ABB.92 TMS374
Fiat Magneti Marelli IAW 1AF.1G TMS374
Fiat Magneti Marelli IAW 4Q-J-W MC68HC11E1
Fiat Magneti Marelli IAW 8F.XX MC68HC11F1
Fiat Magneti Marelli IAW 8P.XX MC68HC11A1
Fiat Bosch M1.7 27C256
Fiat Bosch M2.10.3 24C02

Fiat Bosch M2.10.4 24C02
Fiat Bosch M2.7 27C256
Fiat Bosch M3.8.2 24C02
Fiat Bosch MA 1.7.3 24C02
Fiat Bosch ME 7.9.10 95080
Fiat Bosch ME 7.9.10 95160
Fiat Bosch ME 7.9.6 95080
Fiat Magneti Marelli MJD 6F3 95320
Fiat Magneti Marelli MJD 6F3 v2 95320
Fiat Magneti Marelli MJD 6J3 95320
Fiat Magneti Marelli MJD 6J3 v2 95320
Fiat Magneti Marelli MJD 8DF and 8F2 virgin 95640
Fiat Bosch Motronic MP3.2 93CS46
Fiat Bosch MSA EDC1.3.1 93C46
Fiat GM Multec socket red and brown MC68HC11F1
Fiat GM Multec socket red and white MC68HC11F1
Ford Bosch EDC16C3 95160
Ford Bosch M3.8.1 24C02
Ford Bosch ME7.1 95040
Ford Bosch MSA 15.X 24C02
Ford Siemens SID 804 29F400
Guzzi Magneti Marelli 59M Hybrid ST10F269
Guzzi Magneti Marelli 59M Hybrid v2 ST10F269
Guzzi Magneti Marelli 5AM Hybrid ST10F269
Guzzi Magneti Marelli 5AM Hybrid v2 ST10F269
Honda Bosch EDC15C7 95P08
Honda Bosch EDC16C31 95160
Honda Bosch MSA 11 EDC1.3.1 93C46
Honda Hitachi P9L 93C56
Hyundai Kefico 95160
Hyundai Zexel 93C46
Hyundai Kefico Accent 29F400
Hyundai Bosch EDC15C7 95P08
Hyundai Siemens S-11 - ATOC 1000cc - DOHC 27C512
Hyundai Siemens S-11 - ATOC 1100cc - DOHC 27C512
Hyundai Kefico X170 27C512
Isuzu Bosch EDC15M 24C04
Iveco Bosch EDC15C7 95P08
Iveco Bosch EDC15C8 1.31 95320
Iveco Bosch EDC16C39 95320
Iveco Bosch EDC16C39 95640
Iveco Bosch EDC16C8 95640
Iveco Bosch EDC7 95640
Iveco Bosch EDC7 v2 95640
Iveco Bosch MS 6.2 24C16
Iveco Bosch MS 6.3 24C16
Jeep Bosch EDC MSA 15.5-5.3 24C04
Jeep Bosch EDC MSA 15.5-5.3 v2 24C04
Jeep Bosch EDC MSA 15.5-5.5 24C02
Jeep Bosch EDC MSA 15.5-5.5 v2 24C02
Jeep Bosch EDC15C2 95P08
KIA Siemens TMS374
KIA Zexel 93C46
KIA Bosch EDC15C7 95P08

KIA Zexel K04R OKI M951G(93C46)
KIA Zexel K04R OKI M951G(93C56)
KIA KIA MOST K2BC 24LC02
KIA Siemens K348 1300cc 28F512
KIA KIA MOST K9AB EU 27C512
KIA KIA MOST K9BA 27C512
KIA KIA MOST K9BC 27C512
KIA Siemens KC11C 1300cc 28F512
KIA Siemens S-II 1500cc - DOHC 27C512
Kawasaki Denso 93C66
Lada TMS374
Lada BOSCH IMMO MP 7.0 and 7.3 24C02
Lada Bosch M 7.9.7 95080
Lada Bosch M1.5.4 24C02
Lada Bosch MP 7.0 24C02
Lada Bosch MP 7.3 24C02
Lancia Hitachi 24C02
Lancia Hitachi 59C11
Lancia Hitachi 93C46
Lancia Magneti Marelli 1AB.XX 27C512
Lancia Magneti Marelli 1AF.13-14-15-16-17 27C512
Lancia Magneti Marelli 48P 29F400
Lancia Magneti Marelli 48P.3X 95080
Lancia Magneti Marelli 49F 95040
Lancia Magneti Marelli 49F v1 95040
Lancia Magneti Marelli 49F v2 95040
Lancia Magneti Marelli 4AF 95160
Lancia Magneti Marelli 4AF v2 95160
Lancia Magneti Marelli 4EF 95080
Lancia Magneti Marelli 4EF v2 95080
Lancia Magneti Marelli 4GF 95040
Lancia Magneti Marelli 4GF v2 95040
Lancia Magneti Marelli 4MP 29F200
Lancia Magneti Marelli 4SF ST10F280
Lancia Magneti Marelli 59F Hybrid HW ver.100 ST10F269
Lancia Magneti Marelli 59F Hybrid HW ver.100 v2 ST10F269
Lancia Magneti Marelli 5AF Hybrid ST10F269
Lancia Magneti Marelli 5AF Hybrid v2 ST10F269
Lancia Magneti Marelli 5NF 95160
Lancia Magneti Marelli 5NF v2 95160
Lancia Magneti Marelli 5SF 95160
Lancia Bosch EDC15C2 95P08
Lancia Bosch EDC15C5 (5 socket) 24C04
Lancia Bosch EDC15C6 95P08
Lancia Bosch EDC15C7 95P08
Lancia Bosch EDC16C39 95320
Lancia Bosch EDC16C39 95640
Lancia Bosch EDC16C8 95160
Lancia Bosch EDC16C9 95160
Lancia Lucas EPIC MC68HC11E9
Lancia Magneti Marelli IAW 16F.XX MC68HC11F1
Lancia Magneti Marelli IAW 18F.XX MC68HC11F1
Lancia Magneti Marelli IAW 1ABB.92 TMS374
Lancia Magneti Marelli IAW 1AF.1G TMS374

Lancia Magneti Marelli IAW 4Q-J-W MC68HC11E1
Lancia Magneti Marelli IAW 4Q5 27C256
Lancia Magneti Marelli IAW 8F.XX MC68HC11F1
Lancia Magneti Marelli IAW 8P.XX MC68HC11A1
Lancia Bosch M2.10.3 24C02
Lancia Bosch M2.10.4 24C02
Lancia Bosch M2.7 24C256
Lancia Bosch MA 1.7.3 24C02
Lancia Bosch ME 7.9.10 95080
Lancia Magneti Marelli MJD 6F3 95320
Lancia Magneti Marelli MJD 6F3 v2 95320
Lancia Magneti Marelli MJD 6J3 95320
Lancia Magneti Marelli MJD 6J3 v2 95320
Lancia Magneti Marelli MJD 8DF and 8F2 95640
Lancia Bosch MP3.2 93CS46
Lancia Bosch MSA 11 EDC1.3.1 93C46
Lancia GM Multec socket red and brown MC68HC11F1
Lancia GM Multec socket red and white MC68HC11F1
LandRover MEMS 1.9 MKC 93C46
LandRover MSB 1011XX (socket red and black) 93C46
LandRover MSB 1011XX (socket red and black) 93C66
LandRover MEMS 3 93C66
LandRover Bosch EDC15C4 95080
LandRover Bosch EDC15M 24C04
LandRover MEMS MKC 93C46
LandRover Bosch MSA 11 EDC1.3.1 93C46
LandRover Bosch MSA 15.5 93C46
LandRover ROVER MSB 93C46
LandRover Siemens SID 901 29F400
Lexus Denso 93C56
MAN Bosch EDC7 95640
MAN Bosch EDC7 v2 95640
MAN Bosch MS6.1 24C16
MG Bosch EDC15C4 95P08
MG Siemens EMS 2 29F400
MG Siemens EMS 2 v2 29F400
MG Bosch MSA 11 EDC1.3.1 93C46
MV_Agusta Magneti Marelli 59M Hybrid ST10F269
MV_Agusta Magneti Marelli 59M Hybrid v2 ST10F269
MV_Agusta Magneti Marelli 5AM Hybrid ST10F269
MV_Agusta Magneti Marelli 5AM Hybrid v2 ST10F269
Mazda Denso 93C56
Mazda Bosch EDC16C3 95160
Mazda Siemens SID 802 29F400
Mazda Siemens SID 804 29F400
Mercedes Lucas 27C010
Mercedes Lucas MC68HC11E9
Mercedes Default DAS EDC15 CR1 Diesel 24C04
Mercedes Default DAS EDC15 CR2 Diesel 95P08
Mercedes Default DAS EDC16CP3 Diesel 95P08
Mercedes Default DAS HFM VDO 24C04
Mercedes Default DAS ME2.0 MC68HC11
Mercedes Default DAS Temic Diesel AutoSync 95P08
Mercedes Bosch EDC15.5 24C02

Mercedes Bosch EDC15C0 24C04
Mercedes Bosch EDC15C6 v1 95080
Mercedes Bosch EDC15C6 v2 95080
Mercedes Bosch EDC16 v1 95320
Mercedes Bosch EDC16 v2 95320
Mercedes Bosch EDC16C2 95160
Mercedes Siemens Immo Class-A 1.7 CDI MC68HC05
Mercedes Bosch ME 2.0 MC68HC11E9
Mercedes Bosch ME 2.1 MC68HC11E9
Mercedes Siemens VDO Repair MSE H10 v1 29F200
Mercedes Siemens VDO Repair MSE H10 v2 29F200
Mercedes Siemens VDO Repair MSM 1.X v1 29F200
Mercedes Siemens VDO Repair MSM 1.X v2 29F200
Mercedes Temic Truck 93C66
Mercedes Sprinter Temic Immo Repair Start Error MC68HC08
Mercedes Vito Temic Immo Repair Start Error MC68HC05
Mercedes Vito Temic Immo Repair Start Error MC68HC08
Mini MEMS 3 93C66
Mini Bosch EDC15C4 95080
Mini MEMS MKS 93C46
Mitsubishi Bosch EDC15C3 95P08
Mitsubishi Bosch EDC16 95160
Morini Magneti Marelli 59M Hybrid ST10F269
Morini Magneti Marelli 59M Hybrid v2 ST10F269
Morini Magneti Marelli 5AM Hybrid ST10F269
Morini Magneti Marelli 5AM Hybrid v2 ST10F269
NewHolland Bosch EDC7 95640
NewHolland Bosch EDC7 v2 95640
Nissan Lucas 93C46
Nissan Delphi DCM 1.2 95160
Nissan Delphi DCM 1.2 v2 95160
Nissan Bosch EDC15C3 95P08
Nissan Bosch EDC16C3 95160
Nissan Bosch EDC16C36 Virgin 95320
Nissan Siemens EMS 3132 29F200
Nissan Bosch M1.9.5 93C46
Nissan Bosch MSA 15.5-6 24C02
Nissan Bosch MSA 15.5-6 v2 24C02
Nissan Delphi TRW 95080
Nissan Delphi TRW DDCR 95080
Nissan Bosch Truck MS6.4 24C16
Nissan Almera Bosch EDC15C7 24C04
Opel_Vauxhall Simtec 56.1 93C56
Opel_Vauxhall Simtec 56.1 v2 93C56
Opel_Vauxhall Simtec 56.5 27C010
Opel_Vauxhall Bosch EDC15C13 Virgin 5P08C3
Opel_Vauxhall Bosch EDC15C3 95P08
Opel_Vauxhall Bosch EDC15M 24C04
Opel_Vauxhall Bosch EDC15M v2 24C04
Opel_Vauxhall Bosch EDC16C9 95160
Opel_Vauxhall Bosch M1.5.X 24C02
Opel_Vauxhall Bosch M2.8 24C02
Opel_Vauxhall Bosch ME 7.9.6 95080
Opel_Vauxhall Magneti Marelli MJD 6F3 95320

Opel_Vauxhall Magneti Marelli MJD 6F3 v2 95320
Opel_Vauxhall Magneti Marelli MJD 6J3 95320
Opel_Vauxhall Magneti Marelli MJD 6J3 v2 95320
Opel_Vauxhall Magneti Marelli MJD 6JF 95320
Opel_Vauxhall Magneti Marelli MJD 6JO 95320
Opel_Vauxhall Bosch MSA 11 EDC1.3.1 93C46
Opel_Vauxhall Bosch MSA 15.X 24C02
Opel_Vauxhall GM Multec socket blue MC68HC11F1
Opel_Vauxhall GM Multec socket blue and grey 27C256
Opel_Vauxhall GM Multec socket blue and grey MC68HC11F1
Opel_Vauxhall GM Multec socket red and brown MC68HC11F1
Opel_Vauxhall GM Multec socket red and white MC68HC11F1
Opel_Vauxhall GM Multec socket violet MC68HC11F1
Peugeot Johnson Valeo 95160
Peugeot Bosch Motronic MP 3.1 93CS46
Peugeot Johnson Valeo v2 95160
Peugeot Magneti Marelli 1AF.13-14-15-16-17 27C512
Peugeot Magneti Marelli 48P 29F400
Peugeot Magneti Marelli 48P.10 29F200
Peugeot Magneti Marelli 48P.3X 95080
Peugeot Magneti Marelli 48P2.70 29F400
Peugeot Magneti Marelli 48P2.XX 29F400
Peugeot Magneti Marelli 4MP.XX 29F200
Peugeot Magneti Marelli 4MP2.XX 29F200
Peugeot Magneti Marelli 5NP 95160
Peugeot Visteon DCU 102 ST10F276
Peugeot Bosch EDC15C2 (1 socket) 29F400
Peugeot Bosch EDC15C2 (3 socket) 29F400
Peugeot Bosch EDC15C2 (3 socket) 95P08
Peugeot Bosch EDC15C6 95080
Peugeot Bosch EDC15C7 95P08
Peugeot Bosch EDC16C0 95160
Peugeot Bosch EDC16C3 95160
Peugeot Bosch EDC16C34 95160
Peugeot Bosch EDC16C34 Virgin 95160
Peugeot Lucas EPIC MC68HC11E9
Peugeot Magneti Marelli G6 MC68HC11A1
Peugeot Magneti Marelli IAW 1AP.20 TMS
Peugeot Magneti Marelli IAW 1AP.40 TMS
Peugeot Magneti Marelli IAW 1AP.41 TMS
Peugeot Magneti Marelli IAW 1AP.43 TMS
Peugeot Magneti Marelli IAW 1AP.80 TMS
Peugeot Magneti Marelli IAW 1AP.81 TMS
Peugeot Magneti Marelli IAW 1AP.83 TMS
Peugeot Magneti Marelli IAW 1AP.90 TMS
Peugeot Magneti Marelli IAW 6LPX.XX ST10F280
Peugeot Magneti Marelli IAW 8P.XX MC68HC11A1
Peugeot Bosch MA 3.0 93CS46
Peugeot Bosch MA 3.1 v1 93CS46
Peugeot Bosch ME 7.4.4 29F400
Peugeot Bosch ME 7.4.4 v1 95160
Peugeot Bosch ME 7.4.4 v2 95160
Peugeot Bosch Motronic MP 3.2 93CS46
Peugeot Bosch Motronic MP 5.1 93CS46

Peugeot Bosch Motronic MP 5.1.1 93CS46
Peugeot Bosch Motronic MP 5.2 93CS46
Peugeot Bosch Motronic MP 7.0 24C02
Peugeot Bosch Motronic MP 7.2 24C02
Peugeot Bosch Motronic MP 7.3 24C02
Peugeot Bosch MSA 11 EDC1.3.8 93C46
Peugeot Sagem S2000 95080
Peugeot Sagem S2000RPM 95080
Peugeot Siemens SID 801 v1 95C56
Peugeot Siemens SID 801 v2 29F400
Peugeot Siemens SID 801A 29F400
Peugeot Siemens SID 801A v1 95C56
Peugeot Siemens SID 802 29F400
Peugeot Siemens SID 804 29F400
Peugeot Siemens SID 806 29F400
Peugeot Sagem SL96 1x28F512 TMS374
Peugeot Sagem SL96 2x28F512 TMS374
Peugeot 107 Valeo Immo 1000cc 24C04
Peugeot 206 Siemens BSI HDI Virgin v3 95160
Peugeot 206 Siemens BSI Virgin v1 95160
Peugeot 206 Siemens BSI Virgin v2 95160
Peugeot 307 BSI Virgin 95160
Peugeot 307 BSI Virgin v2 95160
Peugeot Partner Siemens BSI Virgin 95160
Porsche Bosch ME 7.1 95040
Porsche Bosch ME 7.1.1 95160
Porsche Bosch ME 7.1.1 95P08
Porsche Bosch ME 7.8 5P08C3
Renault Magneti Marelli 5NP.01 Hybrid 95160
Renault Magneti Marelli 5NR.CE1 Hybrid 95160
Renault Magneti Marelli 5NR.T1 Hybrid 95160
Renault Magneti Marelli 5NR2-C2 95160
Renault Magneti Marelli 5NR2-C5 95160
Renault Magneti Marelli 5NR2-C5 v2 95160
Renault Magneti Marelli 5NR2-K5 v2 95160
Renault Bosch DCM 1.2 95160
Renault Bosch DCM 1.2 v2 95160
Renault Lucas DCU3R 95080
Renault Lucas DCU3R v2 95080
Renault Bosch EDC15 (1 socket) 24C02
Renault Bosch EDC15 (2 socket) 24C04
Renault Bosch EDC15C13 Virgin 5P08C3
Renault Bosch EDC15C3 (3 socket) 5P08C3
Renault Bosch EDC16C3 v1 95160
Renault Bosch EDC16C3 v2 95160
Renault Bosch EDC16C34 95160
Renault Bosch EDC16C34 Virgin 95160
Renault Bosch EDC16C36 Virgin 95320
Renault Bosch EDC16C6 95320
Renault Siemens EMS 3132 29F200
Renault Siemens EMS 3134 29F400
Renault Siemens FENIX MC68HC11
Renault Siemens FENIX 3MCU MC68HC11E1
Renault Siemens FENIX 5 TMS374

Renault Siemens HOM BVM MC68HC11E1
Renault Magneti Marelli IAW 6R.20 TMS370
Renault Magneti Marelli IAW 6R.30 TMS370
Renault Magneti Marelli IAW 8R.30 MC68HC11A1
Renault Bosch Motronic MP 7.0 24C02
Renault Bosch MSA 15.5 24C02
Renault Bosch MSA 15.5 v2 24C02
Renault Sagem S2000RPM 95080
Renault Sagem S2000RPM v2 95080
Renault Sagem S3000 Virgin 95160
Renault Siemens SIM32 95160
Renault Siemens SIM32 v2 95160
Renault Siemens SIRIUS 32 without CAN 29F200
Renault Siemens SIRIUS 32 without CAN v2 29F200
Renault Siemens SIRIUS 34 29F200
Renault Siemens SIRIUS 34 29F400
Renault Siemens SIRIUS 34 v2 29F400
Renault Siemens SIRIUS 34 v3 29F400
Renault Siemens SIRIUS 35 29F400
Renault Delphi TRW 95080
Renault Delphi TRW DDCR 95080
Renault Bosch Truck MS6.2 24C16
Renault Bosch Truck MS6.3 24C16
Saab Visteon DCU 102 ST10F276
Saab Bosch EDC15M 24C04
Scania Bosch MS 6.2 24C16
Scoda Magneti Marelli 16S.XX MC68HC11F1
Scoda Digifant 3.2 27C256
Scoda Siemens 5WP4 SIMOS 1.X (1socket) 93C56
Scoda Siemens 5WP4 SIMOS 3.X (2socket) 93C76
Scoda Bosch EDC16CP34 95320
Scoda Bosch EDC16U1 95320
Scoda Bosch EDC16U31 95320
Scoda Bosch EDC16U34 95320
Scoda Bosch M3.2.1 24C02
Scoda Bosch M3.8.X 24C02
Scoda Bosch M3.8.X v2 24C02
Scoda Bosch M5.4.1 24C02
Scoda Bosch M5.9.2 24C02
Scoda Bosch ME 7.X.X 95040
Scoda Bosch ME 7.X.X 95160
Scoda Bosch ME 7.X.X 95P08
Scoda Bosch MED 9.5.10 95080
Scoda Bosch MSA 11 EDC1.3.1 93C46
Scoda Bosch MSA 15.X 24C02
Scoda Siemens SIMOS 7.X 93C86
Scoda Siemens SIMOS 8.1 93C86
Scoda Siemens SIMOS 9.1 93C86
Seat Magneti Marelli 16S.XX MC68HC11F1
Seat Digifant 3.2 27C256
Seat Siemens 5WP4 SIMOS 1.X (1socket) 93C56
Seat Siemens 5WP4 SIMOS 3.X (2socket) 93C76
Seat Bosch EDC16CP34 95320
Seat Bosch EDC16U1 95320

Seat Bosch EDC16U31 95320
Seat Bosch EDC16U34 95320
Seat Bosch M3.2.1 24C02
Seat Bosch M3.8.X 24C02
Seat Bosch M3.8.X v2 24C02
Seat Bosch M5.4.1 24C02
Seat Bosch M5.9.2 24C02
Seat Bosch ME 7.X.X 95040
Seat Bosch ME 7.X.X 95160
Seat Bosch ME 7.X.X 95P08
Seat Bosch MED 9.5.10 95080
Seat Bosch MSA 11 EDC1.3.1 93C46
Seat Bosch MSA 15.X 24C02
Seat Siemens SIMOS 7.X 93C86
Seat Siemens SIMOS 8.1 93C86
Seat Siemens SIMOS 9.1 93C86
Smart Bosch EDC15CG 95P08
Smart Bosch MEG 1.0 24C02
SsangYong Delphi Rexton 95160
Suzuki Hitachi 93LC56
Suzuki Delphi DCM 1.2 95160
Suzuki Delphi DCM 1.2 v2 95160
Suzuki Lucas DCU3R 95080
Suzuki Bosch EDC15C2 (1 socket) 29F400
Suzuki Bosch EDC15C2 (3 socket) 29F400
Suzuki Bosch EDC15C2 (3 socket) 95P08
Suzuki Bosch EDC15C3 95160
Suzuki Magneti Marelli MJD 6F3 95320
Suzuki Magneti Marelli MJD 6J3 95320
Suzuki Magneti Marelli MJD 6J3 v2 95320
Suzuki Magneti Marelli MJD 6JF 95320
Suzuki Siemens SID801 29F400
Suzuki Siemens SID801 93C56
Suzuki Siemens SID801A 29F400
Suzuki Siemens SID801A 93C56
Suzuki Delphi TRW 95080
Suzuki Delphi TRW DDCR 95080
Toyota Denso D4D 93C86
Toyota Bosch EDC16C 95160
Toyota Aygo Valeo Immo 1000cc Virgin 24C04
Toyota Yaris Bosch 5 socket Virgin 95080
VW Magneti Marelli 1AV 27C512
VW Digifant 3.2 27C256
VW Magneti Marelli 4MV.XX Virgin 95080
VW Siemens 5WP4 SIMOS 1.X (1 socket) 93C56
VW Siemens 5WP4 SIMOS 3.X (2 socket) 93C76
VW Bosch EDC15C4 5P08C3
VW Bosch EDC16CP34 95320
VW Bosch EDC16U1 95320
VW Bosch EDC16U31 95320
VW Bosch EDC16U34 95320
VW Bosch M2.3.2 27C512
VW Bosch M3.2.1 24C02
VW Bosch M3.8.X 24C02

VW Bosch M3.8.X v2 24C02
VW Bosch M5.4.1 24C02
VW Bosch M5.9.2 24C02
VW Bosch MA 1.2.3 27C512
VW Bosch MA 1.3 1600cc 87C510
VW Bosch ME 7.X.X 95040
VW Bosch ME 7.X.X 95080
VW Bosch ME 7.X.X 95160
VW Bosch MED 9.5.10 95080
VW Bosch MSA 11 EDC 1.3.1 93C46
VW Bosch MSA 12 EDC 1.3.1 93C46
VW Bosch MSA 15.X 24C02
VW Siemens SIMOS 7.X 93C86
VW Siemens SIMOS 8.1 93C86
VW Siemens SIMOS 9.1 93C86
Volvo GM Delco 27C256
Volvo Bosch EDC15 (1 socket) 24C02
Volvo Bosch EDC15C3 5P08C3
Volvo Bosch EDC16C31 95160
Volvo Siemens SIRIUS 32 29F200
Volvo Siemens SIRIUS 32 without CAN 29F200
Volvo Bosch Truck EDC7 95640